

00543" 50000000


APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

139  
116.2

3741  
1-9


FIG.1

Loom stopping cause entailing faulty picking




# FIG.2

Loom stopping cause other than faulty picking



Faulty picking (One-shot-starting method)


FIG.3



00540" 9826260

FIG.4


Loom stopping cause entailing faulty picking




APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

FIG.5

Loom stopping cause other than faulty picking




# FIG.6



00293386 0449 003410 3826260

FIG.7




66340-36360

063443 336260

FIG.8

Command to stop a picking operation in the next weaving cycle





APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

FIG.9

